National Transportation Safety Board NTSB ID: ATL00LA018 Aircraft Registration Number: N1315A FACTUAL REPORT Occurrence Date: 12/23/1999 Most Critical Injury: Serious Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone PR 1600 **ADJUNTAS** 00601 **EST** Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Cessna 208B Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On December 23, 1999, at 1600 atlantic standard time, a Cessna 208B, N1315A, collided with trees in a heavily wooded area near Adjuntas, Puerto Rico. The air taxi cargo flight was operated by M & N Aviation under the provisions of Title 14 CFR Part 135 with no flight plan filed. Visual weather conditions prevailed at the nearest weather reporting facility at the time of the accident. The airplane sustained substantial damage. The commercial pilot received minor injuries and his passenger received serious injuries. The flight departed Ponce, Puerto Rico, at 1532.

While en route to Ponce, the pilot heard a radio transmission that weather conditions in the vicinity of his next destination was "bad." Upon arriving in Ponce, the pilot attempted to telephone Flight Service for a weather briefing and to file a flight plan. After efforts to contact Flight Service failed, the pilot elected to takeoff without filing a flight plan. After a few minutes into the flight, the pilot decided to return to Ponce. Reportedly, the flight encountered deteriorating weather conditions that included heavy turbulence, and low ceilings. While attempting to maintain visual contact with the ground the pilot anticipated executing a left turn to avoid colliding with the high terrain. The airplane collided with trees as the pilot maneuvered the airplane.

The post-accident examination of the airplane failed to disclose a mechanical malfunction or a component failure. The pilot did not report a mechanical problem with the airplane. A review of the en route flight charts disclosed that the terrain elevation at the departure point was approximately 24 feet. The terrain elevation at the approximate location of the accident site was 2,500 feet.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ATL00LA018

Occurrence Date: 12/23/1999

AVIATION			Occui	Occurrence Type: Accident										
Landing Facility/Approach In	forma	ation												
Airport Name				Airport ID:	: /	Airport Elevati	ion	Run	way Used	Runwa	ay Lengt	th	Runwa	ay Width
					Ft. MSL			. 0						
Runway Surface Type:														
Runway Surface Condition:														
•														
Type Instrument Approach:														
VFR Approach/Landing:														
Aircraft Information														
Aircraft Manufacturer					lel/Se	eries						Serial Number		
Cessna				208	3B ——						208-0	0655		
Airworthiness Certificate(s): Normal														
Landing Gear Type: Tricycle														
Homebuilt Aircraft? No Number of Seats: 2					Certified Max Gross Wt.) LBS	Numbe	er of En	gines:	1
					Engine Manufacturer: Model/Series: P&W PT6A-114A								Rated 675	l Power: HP
- Aircraft Inspection Information														
Type of Last Inspection Da					Date of Last Inspection Time Sin				nce Last Insp	pection		Airfran	ne Tota	al Time
100 Hour				12/02/1	12/02/1999					1343 Hours			14	127 Hours
- Emergency Locator Transmitter (ELT) Information														
ELT Installed? Yes		ELT Operate	d? Yes	S	ELT Aided in Locating Accident Site? No)		
Owner/Operator Information														
Registered Aircraft Owner					Street Address POB 70256									
GE CAPITAL CORP OF P.R.				City	City							State	е	Zip Code
				SAN JUAN								PR	(00936
Operator of Aircraft				Street Address POB 906566										
-				City							State	e	Zip Code	
M&N AVIATION					SAN JUAN						PR		- 1	00906
Operator Does Business As:		Operator Designator Code:												
- Type of U.S. Certificate(s) Held:														
Air Carrier Operating Certificate(s)	: On-c	demand Air T	axi											
Operating Certificate: Operator Certificate:														
Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter														
Type of Flight Operation Conducted: Unknown														
			A CTT	מינות ואו	ODT	r	ONT							Page 2
I		F	ACIL	AL KEP	·OK]	Γ - AVIATIO	JN							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ATL00LA018

Occurrence Date: 12/23/1999

AVIAT	Occurrence Type: Accident													
First Pilot Information														
Name				(City					State	e [Date of Birth	Age	
On File					On F	ile	On				ile	On File	21	
Sex: M Seat Occupie	certificate Number: On File													
Certificate(s): Co														
Airplane Rating(s): Mu	lti ongina La	ndı Cinalo a	naina Land											
Rotorcraft/Glider/LTA: No	Iti-engine Lai	nu, Single-e	engine Land											
, ·														
Instructor Rating(s): None														
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review?														
Medical Cert.: Class 1	Medica	al Cert. Statu	s: Valid Me	dicalno wa	ivers	lim.			Date of La	ast Med	dical Ex	kam: 09/11/19	99	
								•						
- Flight Time Matrix All A/C This Make and Model			Airplane Single Engine	1 · 1 N		ght Instrum		Instrum	ent Simulated	R	otorcraft	Glider	Lighter Than Air	
Total Time	1985	550	1300	685										
Pilot In Command(PIC)														
Instructor														
Last 90 Days														
Last 30 Days														
Last 24 Hours	<u> </u>													
Seatbelt Used? Yes	Shou	ılder Harness	Used? Yes			Toxicology Performed? No Second Pilot? No								
Flight Plan/Itinerary														
Type of Flight Plan Filed: I	None													
Departure Point						State		Airport Identifier			Departure Time		Time Zone	
PONCE						PR		PSE			1532		AST	
Destination						State		Airpo	rt Identifie	er				
AGUADZILLA								Airport Identifier BQN						
Type of Clearance: None)					•	•							
Type of Airspace: Class	s G													
Weather Information														
Source of Briefing: No record of briefing														
Method of Briefing:														
			FACTUAL	REPORT -	AVI	ATION	٧						Page 3	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ATL00LA018

Occurrence Date: 12/23/1999

Occurrence Type: Accident

Weather	Information														
WOF ID	Observation Time	Time Zone	WOF	Elevation	n	WOF Distance From Accident Site					Direction From Accident Site				
D05	40.40			0.4 =:											
PSE	1348	AST		24 Ft.	MSL				30 NM			170 Deg.	Mag.		
Sky/Lowes		2500 Ft. AGL					Condition of Light: Day								
Lowest Ce		0 Ft. AGL			ility:	15	SM	Altimeter: 30		30.00	"Hg				
Temperatu	1	19 °C Wind Direction: 40 Density Altitude: 2000							2000	Ft.					
Wind Spee	ed: 8	Gusts:			Weath	ather Condtions at Accident Site: Visual Conditions									
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensit	y of Precip	oitation:	Unknown						
Restriction	s to Visibility: None														
Type of Pre	ecipitation: None														
Accident Information															
Aircraft Dar	mage:		Airo	raft Fire	:	Aircraft Exp					losion				
Classificati	on:														
- Injury Su	mmary Matrix	Fatal	Serious	rious Minor			TOTAL								
First Pi	lot				1			1							
Second	d Pilot														
Studen	t Pilot														
Flight In	nstructor														
Check	Pilot							7							
Flight E	ngineer							7							
Cabin A	Attendants							7							
Other C	Crew							7							
Passen	gers		1					1							
- TOTAL A	ABOARD -		1		1			2							
Other G	Ground	0	0		0			0							
- GRAND	TOTAL -	0	1		1			2							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: ATL00LA018

Occurrence Date: 12/23/1999

Occurrence Type: Accident

							-			
Δ	dт	ını	ıctı	rativ	10	Int	^rı	മാ	tιΛ	n
$\overline{}$	um		IJΙ	au	v C		OH	III C	เเบ	

Investigator-In-Charge (IIC)

PHILLIP POWELL

Additional Persons Participating in This Accident/Incident Investigation:

JORGE D PEREZ SAN JUAN FSDO SAN JUAN, PR